



PHOTOGRAPHIC RECORD OF RAWLINS PLANTATION INN AND
COST ELEMENT DETAILS FOR REMEDIAL WORKS, PART ONE:

Rawlins Plantation Inn before seizure by FCIB



Photo P1 : View of main Great House building from the
croquet lawn.



Photo P2 : Aerial view of Rawlins Plantation Inn



Photo P3 : North West elevation of Main Great House building



Photo P4 : West verandah with adirondack chairs



Photo P5 : Outer Restaurant, set for lunch with view to croquet lawn.



Photo P6 : Cocktail Lounge, looking south into the outer restaurant.



Photo P7 : Outer Restaurant, looking through to main dining room.



Photo P8 : Outer Restaurant, set for dinner, with view to Saint Eustatius



Photo P9 : Lunch buffet table



Photo P10 : Library Table, looking past the buffet table, into main dining room.



Photo P11 : Cocktail Lounge chairs



Photo P12 : South West Elevation, of main Great House building



Photo P13 : Bandstand and Gazebo.



Photo P14 : Stone Steps, at south east corner.



Photo P15 : Courtyard to inner restaurant.



Photo P16 : Tea at sunset, from Mountainside Cottage.



Photo P17 : Mountainside Cottage, west elevation.



Photo P18 : Mountainside Cottage, bedroom.



Photo P19 : Cattle Mill, built in the early 1800's, the only original intact example in the West Indies.



Photo P20 : Sugar Mill Cottage, north west elevation.



Photo P21 : Sugar Mill Cottage, lounge.



Photo P22 : Pear Tree Cottage, north west elevation.



Photo P23 : Almond Tree Cottage, south elevation.



Photo P24 : Almond Tree Cottage, bedroom.



Photo P25 : Almond Tree Cottage, lounge.



Photo P26 : Sugarcane Cottage, north east elevation.



Photo P27 : Sugarcane Cottage, north elevation.



Photo P28 : Sugarcane Cottage, lounge.